

Battery	Power Supply Bottomside	Processor Bottomside	Processor / Controller Bottomside	SMART FUJITSU MHT2080AT (NN4CT42163T0)	What Happened when I recorded the temps...
96.8F	129.2F	125.6F	128.3F	100.4F	itunes running (sound bad)
91.4F	138.2F	133.2F	136.4F	104.0F	itunes running (sound bad)
96.8F	96.8F	88.2F	90.5F	84.2F	after sleep (sound is good)
86.0F	137.3F	128.8F	132.8F	93.2F	watching dvd (sound bad)
86.0F	136.8F	129.7F	133.7F	95.0F	watching dvd- cold pack on battery (sound bad)
87.8F	136.4F	127.8F	131.4F	95.0F	watching dvd, cold pack on bottom right of pb (sound bad)
87.8F	112.5F	102.2F	106.7F	93.2	trying to cool down by win- dow (sound still bad)
87.8F	11.2F	101.8F	105.3F	93.2F and going down.	I put it to sleep for a sec then woke it up. (sound back to normal aka good)